



## POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

06

SITE NUMBER

LA0981910649

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

## A. SITE NAME

F. Lacy Lease

B. STREET (or other identifier) 0.6 mi. North of LA Hwy 390 and 0.3 mi. West of LA Hwy 27

## C. CITY

Hackberry

## D. STATE

LA

## E. ZIP CODE

70643

## F. COUNTY NAME

Cameron 023

## G. OWNER/OPERATOR (if known)

1. NAME Mrs. Frances Heirs Lacy c/o Miss Lennie Lacy  
4217 Waterwood Drive, Lake Charles, LA 70605

## 2. TELEPHONE NUMBER

## H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☒ 5. PRIVATE ☐ 6. UNKNOWN

## I. SITE DESCRIPTION

29°59'40"N 93°22'12"W

0.25 acre site is an active petroleum well with a pump and one storage tank.  
See "CAM 54", Browns Lake topo map

## J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)

Aerial photographs and FIT windshield survey

## K. DATE IDENTIFIED (mo., day, &amp; yr.)

2-17-87

## L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

Diking is inadequate around both the well and the storage tank. Petroleum and salt water are migrating off site via the adjacent drainage ditch, as evidenced by the dead vegetation, black oily residue, and white crust in the ditch.

SUPERFUND  
FILE

JUL 17 1992

REORGANIZED

Reviewed by  
Date  
6H-ES  
4-13-87

## M. PREPARER INFORMATION

## 1. NAME

R. David Shiels/JoAnn T. Weber

## 2. TELEPHONE NUMBER

(214) 742-6601

## 3. DATE (mo., day, &amp; yr.)

2-23-87

90069359

